

Statement of Reasons – Langley Vale Road, Epsom

Alteration of the extent of the 30mph limit

The existing Speed limit order for Langley Vale Road is incorrect insofar as it does not reflect the de facto positioning of 30mph terminals on the road. The current order states that one side of the 30mph limit starts at “...***a point 140m south-west of its junction with Grosvenor Road***”, when the terminal signs are actually 490m south-west of its junction with Grosvenor Road. This change will bring the order in line with the signs in situ and the restricted section of Langley Vale Road will begin before motorists reach the residential section of Langley Vale.