

**Surrey County Council  
Various Roads in Woking  
(Traffic Regulation) Order 202-**

**Location 1**

Junction – A320 Victoria Way / Forge End (A320 Victoria Way Southbound)  
Prohibition of U-turn for traffic heading southbound on the A320 Victoria Way (except emergency vehicles).

**Justification**

The design instructs drivers to proceed ahead (southbound A320) or turn right into Forge End by means of a green direction arrow within the traffic signal aspects. However, the safety audit requested the addition of a U-turn ban to reduce the risks of drivers attempting this manoeuvre.

**Location 2**

Junction – A320 Victoria Way / Church Street West (A320 Victoria Way northbound)  
Prohibition of U-turn and Right Turn for traffic heading northbound on the A320 Victoria Way (except emergency vehicle).

**Justification**

The design instructs drivers to proceed ahead (Northbound A320) or turn left into Church Street West by means of a green direction arrow within the traffic signal aspects. However, the safety audit requested the addition of a U-turn and Right Turn ban to reduce the risks of drivers attempting this manoeuvre, as there is a drop-off facility provided on the southbound carriageway at this junction at the new hotel entrance.

**Location 3**

Junction – A320 Victoria Way / Church Street West (Church Street West eastbound)  
Prohibition of left turn for traffic approach from Church Street West (except emergency vehicles)

**Justification**

The design indicates that traffic must turn right into A320 Victoria Way by means of green direction arrow within the traffic signal aspects and by means of no left turn signal box signs. This TRO had been approved previously, but due to the delay in the opening of the junction, it requires to be advertised again.

**Location 4**

Junction – A320 Victoria Way / Goldsworth Road (Goldsworth Road westbound)  
One-way order (except emergency vehicles) westbound only from Victoria Way into Goldsworth Road over the initial 21m of Goldsworth Road to the point of the start of the Turn Loop on Goldsworth Road meets the entry lane from Victoria Way.

**Justification**

While investigating the existing TRO in the area, it was identified that this one-way order had been missed during previous highway improvement works in the area. On this basis, it has been included in these proposals.